

Case No.	Respondent	Summary of Findings	Summary of Board Action
JUNE 24, 2008			
M08-021	William J. Taylor Architect #18962	On or about August 2007, Respondent failed to sign, date and seal a set of plans or mark them "preliminary," "draft," or "not for construction" before submitting them to his client's attorney.	<i>Letter of Reprimand</i>
Case No.	Respondent	Summary of Findings	Summary of Board Action
AUGUST 26, 2008			
M08-028	Marty S. Wiers Nonregistrant	On or about August 2007, Respondent prepared a letter for the "Foundations-Over-Excavation" for a residential project that contained engineering recommendations and affixed the seal and signature of a registered P.E. to the letter without the registrant's knowledge.	<i>Assurance of Discontinuance</i> – Respondent shall not practice, offer to practice, or by any implication hold himself out as qualified to practice Engineering, as defined by A.R.S. §§ 32-101(B)(11) and (12); shall not advertise or display any card, sign or other device that may indicate to the public that he is a registered Professional Engineer, or is qualified to practice as such; and shall not assume the title of "Professional", "P.E.", "Registered", "Registered Professional", or "Professional Registered" Engineer within the State of Arizona until Respondent is granted registration by the Board as required by A.R.S. § 32-121. <i>Civil Penalty</i> – Pay a civil penalty of \$1,500.00. <i>Cost of Investigation</i> – Pay cost of investigation in the amount of \$250.00.
M08-057	Michael P. Mancini P.E. (Civil) #37869	On or about August 15, 2005, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent prepared a grading and drainage plan and a drainage report. In preparing his plan and rerouting the wash, Respondent failed to hydraulically evaluate and design a storm water conveyance that would reroute the storm water to exit the site in its pre-existing location; and failed to follow the recommendations stated in his drainage report and designed the residence outside the building envelope encroaching into the existing wash.	<i>Letter of Reprimand</i> <i>Administrative Penalty</i> – Pay an administrative penalty of \$1,000.00. <i>Cost of Investigation</i> – Pay cost of investigation in the amount of \$375.00.
M08-092	Edward E. Henan P.E. (Civil) #22194	On or about November 29, 2007, Respondent failed to apply the technical knowledge and skill that would be applied by other qualified registrants who practice the same profession in the same area and at the same time. Respondent signed and sealed a site suitability investigation report that failed to accurately show the actual soil conditions and the number and depth of bore holes that were excavated. Respondent failed to provide adequate supervision of a nonregistrant employee.	<i>Administrative Penalty</i> – Pay an administrative penalty of \$500.00. <i>Cost of Investigation</i> – Pay cost of investigation in the amount of \$110.00.
M08-093	Joseph B. Sarvis Land Surveyor #15904	On or about October 26, 2006, Respondent failed to conduct a survey in accordance with the Arizona Boundary Survey Minimum Standards. Respondent prepared a Parcel Split which is deficient in that corners on the North line of the survey are not of record; failed to show sufficient ties to controlling monuments; failed to show a basis of bearings, a legend and a list of pertinent reference documents that were used as a basis for the survey; and failed to adequately review his survey before signing, sealing and recording it in the Yavapai County Recorder's office.	<i>Amend Survey</i> – Respondent shall amend his survey and record it with the Yavapai County Recorder's Office. <i>Cost of Investigation</i> – Pay cost of investigation in the amount of \$125.00.